
FLUKE®

Fluke Inspection Services, Inc.


123 Infrared Way
Everett, WA 55427



Prepared for:

Mr. & Mrs. Property Owner
123 Residential Street
Everett, WA 55427

Missing Insulation - Family Room




Visible Light Image

IR000023.is2

12/23/2005 9:27:30 PM

Missing insulation as indicated by the blue color on the image. Due to the vaulted ceiling, the cost of making this repair will likely outweigh the energy savings.

Master Bedroom




Visible Light Image

IR000004.IS2

1/10/2008 12:44:42 PM

Moisture detected above South-facing window with thermal imager and confirmed with moisture meter. Determining source of leak requires further investigation, but is likely to be caused by a roof defect.

Rear Entry Door




Visible Light Image

IR000141.IS2

3/19/2009 12:57:23 PM

Significant air leak detected. Recommend replacing weather stripping.

Electrical Outlet - Kitchen



Visible Light Image

IR000150.IS2

3/19/2009 1:50:33 PM

Air leak detected on electrical outlet on exterior wall in kitchen. Recommend air sealing with foam, caulk or foam gasket.