

Supplement

Manual Title:	FTP/UK Instruction Sheet		
Part Number:	3999608	Supplement Issue:	1
Print Date:	April 2011	Issue Date:	8/18
Revision/Date:		Page Count:	1

This supplement contains information necessary to ensure the accuracy of the above manual.

Change #1, 634

Under **Introduction** replace the first paragraph with:

The Fluke FTP/UK is a CAT III 1000 V/CAT IV 600V Fused Test Probe Set that is used with the Fluke 1650 Series of Installation Testers. The Test Probe uses 11 A 1000 V fuses.

In the **Symbols** table replace the CAT II, CAT III and CAT IV descriptions with:

CAT II	Measurement Category II is applicable to test and measuring circuits connected directly to utilization points (socket outlets and similar points) of the low-voltage MAINS installation.
CAT III	Measurement Category III is applicable to test and measuring circuits connected to the distribution part of the building's low-voltage MAINS installation.
CAT IV	Measurement Category IV is applicable to test and measuring circuits connected at the source of the building's low-voltage MAINS installation.

Under **Warnings**, add:

- **DO NOT USE in CAT III or CAT IV environments without the protective cap installed. The protective cap decreases the exposed probe metal to <4 mm. This decreases the possibility of arc flash from short circuits.**

In the **Configurations** table, Item 1 and 2 replace:

From: GS38 cap

To: Protective cap

Replace the **Specifications** section with:

Maximum voltage between any Terminal and Earth Ground	1000 V
Fuse	1000 V, 11 A 20 kA IR
Safety	IEC 61010-031: CAT II 1000 V (without cap), CAT III 1000 V, CAT IV 600 V (with cap installed), Pollution Degree 2
Duty Cycle	7 A continuous, 10 A five minutes on ten minutes off
Altitude	3000 m